

Fast-blow fuse tube (act-quick).



FUSE S5002

2A

-
- General
 - Construction Glass